

Flowdown Requirements

The supplier is responsible for compliance with all quality and technical requirements imposed by CF/NGC even when the supplier subcontracts part of the work. The supplier's responsibilities with respect to subcontracted work include:

- Transmission (flow down) of applicable quality and technical requirements to subtier suppliers
- Flow down of this provision to their subtier suppliers and verification that this provision has been properly implemented.
- Selection and control of subtier suppliers, unless otherwise specified in the purchase document.
- Assuring traceability of items processed through subtier suppliers It is the supplier's responsibility to assure that the purchase order to the subtier supplier requires sufficient acceptance data to clearly fulfill the requirements imposed by the NGC purchase order to the supplier.